







OWNER:  شرکت سست و سویی آبرسانان (سهایی بخار)	BUSHEHR PETROCHEMICAL COMPANY MEG PLANT						EPC CONTRACTOR:  Chagalesh-Enerchimi-Steam Joint Venture BUPC-MEG PLANT PROJECT		
	TWO YEARS SPARE PART LIST IN SPLIR FORMAT								
MC :  شرکت سست و سویی آبرسانان تهران	Project	Area	Phase	Unit	Dis.	Doc.	Seq.	Contract No : 52-98/445	
Owner Document Number: 17811-42	BU	20	VD	303	ME	LST	0054	Rev.:	Page
								03	1 of 5

Manner of generating SPLIR list, shall be same as sample list given in REV.01 of this document. Please see attached file.



TWO YEARS SPARE PART LIST IN SPLIR FORMAT

 شرکت سست و سویی آبرسانان	 Chagalesh-Enerchimi-Steam Joint Venture BUPC-MEG PLANT PROJECT	BUSHEHR PETROCHEMICAL COMPANY MEG PLANT
Document Review		
Issue Purpose:	IFA	
Result Code: AP,AN,CM,RE,NC	CO	
Next Status : IFC,IFA,IFI,AFC,AB	IFA	
Responsible Department	MECHANICAL	
Commented Date	Sep.13,2023	
Approval or review hereunder shall not be construed to relieve Vendor / Subcontractor of his responsibilities and liability under the contract.		

Rev.	Date	Purpose of Issue	Prepared	Checked	Approved	AC Code
03	31/08/2023	Issue For Approve	KP	MC	JR	
02	14/07/2023	Issue For Approve	MC	KP	JR	
01	07/11/2022	Issue For Approve	MC	KP	JR	
00	10/06/2022	Issue For Approve	KP	CL	JR	
					Class: 1	Phase: P



BUSHEHR PETROCHEMICAL COMPANY MEG PLANT

فهرست قطعات یدکی و اقلام مشابه

SPARE PARTS

Repetitive comment: Other main equipment of compressor 1002 and 7080 shall be written here in individual column (Electrical motor, pulsation dampener, heat exchanger). Please the attached sample file.

Table with columns: EQUIPMENT CLASS, EQUIPMENT RECOMMENDATION, MANUFACTURERS MODEL, MANUFACTURERS SERIAL NO., NO OF UNIT, UNIT, DESCRIPTION OF PARTS, DRAWING/ REF.NO., Manufacturers Real part No., Material, Recommended by manufacturer, Recommended by contractor, 2-Year spares, Quantity to be supplied, MESC NO., Classification of parts, Unit Price, Total Price, Remarks, Item No.

NUMBER OF PARTS PER UNIT/ EQUIPMENT

Two, as per compressor detail drawing.

Complete set is missing (suction valve(complete set)).

6, as per material requisition (300%)

Repetitive comment: - Radial oil seal gaskets (893, 840) for compressor 1002 are missing. - Liner of both stages are missing. - Oil gland seal / wiper is missing. - Gland gas (1027) is missing. - Tube, bolts and gaskets for heat exchanger of C-1002 is missing. Interstage and after cooler shall be written separately.

